



SPECIAL SERVICE INSTRUCTIONS FOR S92 AND STRUCTURAL SUPPORT SERVICES

SSI No. 92-037

Cabin Structural Reinforcement

SSI No. 92-074

Main Transmission Frame, Cold Working of Station 361 and Station 328
Doubler Attachment Holes and Station 328 Side Frame Holes

SSI No. 92-098

Waterline (WL) 252 Longeron Modification of Station (STA) 328

SSI No. 92-099

Modification and Installation of Shoulder Strap

SSI No. 92-105

Main Transmission Frame - Modification of Station (STA) 361 Frame

SSI No. 92-116

Static Airframe Doubler Kit

SSI No. 92-183

TRAKKABEAM A800 System Provisions

1500 Hour Inspection Structural Support

Firewall Curtains and Shroud Repairs

